

Village of East Aurora: Reconnaissance Level Survey

246 Gleed Avenue v1946

One-and-a-half-story brick and frame house, an intact and unusually exceptional early post-war example.



163 Green Street v1920

Two-story frame house, a very good example of a Craftsman bungalow.



168 Green Street v1925

Two-story frame house, an intact Colonial Revival example. Although a full two stories, the front gable arrangement suggests a cozier one-and-a-half-story house.



480 Griggs Place v1917

Two-and-a-half-story frame house, a good example of a symmetrical Colonial Revival design with an unusual fenestration pattern.



Village of East Aurora: Reconnaissance Level Survey

19 Hamburg Street c1910

Two-and-a-half-story frame house, a very intact and unusual vernacular design with an integral two-story front porch above a fieldstone foundation.



19 Hamlin Avenue c1870

Two-story frame house, a good, intact example of a simple vernacular front gabled house, with an exceptional front porch. It was likely moved here in 1920, probably from Main Street.



28 Hamlin Avenue c1870

One-and-a-half-story frame house, a highly unusual example of the Second Empire style, which appears to be one half of square mansard roof house with a smaller section grafted on. It was likely moved here in 1927, probably from Main Street.



85 Hamlin Avenue v1926

One-and-a-half-story frame house, a very good example of a vernacular bungalow.



Village of East Aurora: Reconnaissance Level Survey

102 Hamlin Avenue v1951

One-and-a-half-story frame house, a good postwar example of the Cape Cod style.



107 Hamlin Avenue v1926

One-story frame house, good example of a Craftsman bungalow.



141 Hamlin Avenue v1930

Two-and-a-half-story frame house, a very good example of Dutch Colonial Revival.



159 Hamlin Avenue v1925

Two-story frame house, a well preserved vernacular example.



Village of East Aurora: Reconnaissance Level Survey

176 Hamlin Avenue v1952

One-story frame house, a good postwar example of the Ranch style.



184 Hamlin Avenue v1947

One-and-a-half-story frame house, a good postwar example of the Cape Cod style.



190 Hamlin Avenue v1948

Two-story brick house, a well preserved postwar vernacular example.



49 Kolver Court c1850

Two-story frame house, an outstanding, very well preserved example of front gable with side wing Greek Revival house. It was apparently moved here from Main Street in 1921.

Recommended NRE (I)

Previously inventoried in 1970s



Village of East Aurora: Reconnaissance Level Survey

157 King Street v1900

Two-story frame house, a well preserved vernacular example.



191 King Street v1900

Two-story frame house, a well preserved vernacular example.



214 King Street v1952

One-and-a-half-story frame house, notable despite later alterations as one of the few log houses in the Village.



220 King Street v1920

Two-story frame house, a good example of the American Foursquare.



Village of East Aurora: Reconnaissance Level Survey

115 Knox Road v1900

One-and-a-half-story frame house, a very good example of a Colonial Revival bungalow.



760 Lawrence Avenue v1928

Two-and-a-half-story frame house, a very good Colonial Revival example.

Contributing building in the proposed Pine Street historic district.



761 Lawrence Avenue v1926

Two-and-a-half-story frame house, an outstanding, intact example of the Tudor Revival style.

Contributing building in the proposed Pine Street historic district.



817 Lawrence Avenue c1950

Two-story brick apartment building, an unusual Colonial Revival design.



Village of East Aurora: Reconnaissance Level Survey

843 Lawrence Avenue v1929

One-and-a-half-story frame house, an unusual side gable Colonial Revival style bungalow with clipped gables.



356 Linden Avenue v1920

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



362 Linden Avenue v1952

One-story concrete block house, an unusual use of this material in a postwar Ranch house.

Contributing building in the proposed South Village historic district.



370 Linden Avenue v1925

One-and-a-half-story frame house, a good example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

371 Linden Avenue v1950

One-story brick, stone and frame house, an exceptional postwar Ranch house unusual fieldstone and brick work.

Contributing building in the proposed South Village historic district.



382 Linden Avenue v1910

Two-and-a-half-story frame house, a good example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



391 Linden Avenue v1915

Two-and-a-half-story frame house, a good Colonial Revival example.

Contributing building in the proposed South Village historic district.



395 Linden Avenue v1906

Two-and-a-half-story frame house, an excellent Colonial Revival example.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

400 Linden Avenue v1917

Two-and-a-half-story frame house, a very good Craftsman example.

Contributing building in the proposed South Village historic district.



414 Linden Avenue v1926

Two-and-a-half-story frame house, a very good example of the Craftsman style.

Contributing building in the proposed South Village historic district.



421 Linden Avenue v1911

Two-and-a-half-story frame house, an exceptional and unusual example of the Queen Anne style.

Contributing building in the proposed South Village historic district.



432 Linden Avenue v1925

Two-story frame house, a very good example of the Craftsman style.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

448 Linden Avenue v1902

Two-and-a-half-story frame house, a very good example of the Queen Anne style.

Contributing building in the proposed South Village historic district.



459 Linden Avenue v1948

One-story brick house, an unusually well done postwar Ranch house with notable brickwork.

Contributing building in the proposed South Village historic district.



460 Linden Avenue v1892

Two-story frame house, an excellent example of the Queen Anne style.

Contributing building in the proposed South Village historic district.



478 Linden Avenue v1925

Two-and-a-half-story brick and stucco house, a good Colonial Revival example.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

481 Linden Avenue v1914

Two-and-a-half-story frame house, a very good example of the Craftsman style.

Contributing building in the proposed South Village historic district.



484 Linden Avenue v1910

Two-and-a-half-story frame house, a very good example of the late shingled Queen Anne style.

Contributing building in the proposed South Village historic district.



485 Linden Avenue v1920

Two-and-a-half-story frame house, a good example of the Craftsman style.

Contributing building in the proposed South Village historic district.



191 Linden Avenue v1912

One-and-a-half-story frame house, a very good example of a vernacular bungalow.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

498 Linden Avenue v1924

One-and-a-half-story frame house, a well preserved vernacular example.

Contributing building in the proposed South Village historic district.



502 Linden Avenue v1924

Two-and-a-half-story frame house, a good, intact example of the Craftsman style.

Contributing building in the proposed South Village historic district.



511 Linden Avenue v1914

Two-and-a-half-story frame house, a good Craftsman example.

Contributing building in the proposed South Village historic district.



517 Linden Avenue v1923

Two-and-a-half-story frame house, a very good example of Dutch Colonial Revival.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

525 Linden Avenue v1925

Two-and-a-half-story frame house, a well preserved Tudor style example.

Contributing building in the proposed South Village historic district.



528 Linden Avenue v1925

Two-and-a-half-story frame house, a good Colonial Revival example.

Contributing building in the proposed South Village historic district.



536 Linden Avenue v1923

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



537 Linden Avenue v1907

Two-and-a-half-story frame house, an excellent example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



Village of East Aurora: Reconnaissance Level Survey

552 Linden Avenue c1950

One-story frame commercial building in the form of a postwar Ranch house.

Contributing building in the proposed South Village historic district.



563 Linden Avenue v1920

One-and-a-half-story frame house, a good example of a Craftsman bungalow.

Contributing building in the proposed South Village historic district.



568 Linden Avenue v1927

Two-and-a-half-story frame house, an unusual Craftsman example.



581 Linden Avenue v1927

Two-and-a-half-story frame house, a good example of the Craftsman style with a very dramatic porch roof.



Village of East Aurora: Reconnaissance Level Survey

187 Main Street c1860

Two-and-a-half-story brick house, an early building notable, despite storefront addition, for the slightly pointed arch windows.

USN 02952.000104 (N)



259 Main Street 1840

Two-story frame house, a good, intact example of a front gable and wing Greek Revival dwelling.

Previously inventoried in 1977

USN 02952.000116 (N)



305 Main Street v1875

Two-and-a-half-story frame house, a well preserved example of the Italianate style.

Previously inventoried in 1977

USN 02952.000122 (I)



319 Main Street v1826

Two-and-a-half-story frame house, a well preserved and unusual example of the Federal style, with a large barn at rear.

Previously inventoried in 1977, 1981

USN 02952.000057 (I)



Village of East Aurora: Reconnaissance Level Survey

340 Main Street 1828

Two-and-a-half-story frame house, a classic five-bay example of the Federal style, notable despite modern siding.

Previously inventoried in 1970s, 1981

USN 02952.000127



345 Main Street 1927

Charles W. Bolton & Son, architects

Baker Memorial Methodist Church, an outstanding Gothic stone religious complex on a prominent corner; added to the National Register in 2012; inventoried in 1970s.

USN 02952.000129 (L)



367 Main Street 1907

First Church of Christ, Scientist, an interesting design of half-timber and stucco above rusticated concrete block. The roof cupola was removed in 1976.

Previously inventoried in 1970s

USN 02952.000131



374 Main Street 1928

North & Shelgren, architects

St. Mathias Episcopal Church, an excellent Gothic stone religious complex on a prominent corner by a notable local firm.

Previously inventoried in 1970s

USN 02952.000132



Village of East Aurora: Reconnaissance Level Survey

411 Main Street c1861

Two-and-a-half-story brick house, an very well preserved Italianate style front gable and wing house which retains its paired brackets and, amazingly, original windows.

Previously inventoried in 1970s

USN 02952.000001 (I)



430 Main Street 1917

Harris & Merritt, architects

An imposing three-story brick school at a major intersection, with large additions built in 1927, 1933 (both by Aaron R. Merritt), 1954 and 1964.

USN 02952.000144 (I)



464 Main Street 1904 / 1963

East Aurora Christian Church, a traditional rusticated concrete block and frame church design radically altered to its present form in 1963 by local architect Clarence E. Donath; a notable example of early 1960s modernism.

Previously inventoried in 1970s

USN 02952.000147 (N)



471 Main Street 1886

Cyrus K. Porter, architect

Two-and-a-half-story frame house, an excellent, very well preserved example of the Queen Anne style in spite of the post-1950 storefront.

Previously inventoried in 1970s

USN 02952.000148 (N)



Village of East Aurora: Reconnaissance Level Survey

478 Main Street c1880

Two-and-a-half-story frame house, a good example of the Queen Anne style that retains its historic form despite mid-20th century alterations.

Previously inventoried in 1970s

USN 02952.000150 (N)



484 Main Street c1910

Two-story frame house, an excellent Colonial Revival design.

USN 02952.000152



502 Main Street c1880

Two-story frame house, a very good example of the Queen Anne style.

Barn previously inventoried in 1970s

USN 02952.000154



509 Main Street v1860

Two-story frame house, a notable square Italianate design that retains its original brackets.

Previously inventoried in 1981

USN 02952.000058 (I)



Village of East Aurora: Reconnaissance Level Survey

530 Main Street c1890

Two-and-a-half-story frame house, a very well preserved example of the Queen Anne style.

Previously inventoried in 1970s

USN 02952.000161



550 Main Street 1963

Clarence E. Donath, architect

One-story brick public library, a good and little changed example of 1960s modernism in the Village.

USN 02952.000163



571 Main Street 1929

North & Shelgren, architects

Two-story brick Village office building, a very well preserved design by a prominent architectural firm.

USN 02952.000082 (I)



574-6 Main Street c1910

Two-and-a-half story brick commercial building with stone lintels and a false front projecting above the roofline. Originally contained a hall for the International Order of Odd Fellows (I.O.O.F.) on the second floor.

USN 02952.000206



Village of East Aurora: Reconnaissance Level Survey

Main Street Railroad Bridge 1934

Concrete and metal railroad bridge, one of four built by the Pennsylvania Railroad when it raised the elevation of its tracks through the Village in the early 1930s.

USN 02952.000208 (I)



617 Main Street c1925

One-story stucco gas station, an exceptional and intact design that still retains its tile roof. Notable despite the later rear garage addition.

USN 02952.000169



634 Main Street 1917

A. E. Baxter, architect and engineer

Two and five-story reinforced concrete grain elevator and mill designed by one of Buffalo's foremost industrial firms. The two easternmost bays is a recent addition.

USN 02952.000171



643 Main Street 1906

Esenwein & Johnson, architects

Three-story stone fraternal building with an imposing Ionic portico, built as the Blazing Star Lodge Masonic Temple.

Previously inventoried in 1970s

USN 02952.000015 (I)



Village of East Aurora: Reconnaissance Level Survey

649 Main Street 1923

One and two-story brick and stone bank building, an excellent example of the Neoclassical style. Built for the Bank of East Aurora.

Previously inventoried in 1970s

USN 02952.000016 (I)



650 Main Street 1917

One-story brick commercial building, a good, notable design despite storefront modifications. Built for Seaman, Hood & Morey.

USN 02952.000174



652-6 Main Street c1930

Two-story brick commercial building, a good, notable design despite storefront modifications. The treatment of the second story is very unusual.

USN 02952.000176



653 Main Street c1930

One-story brick commercial building, an excellent and largely intact design that still retains its transom windows.

USN 02952.000175



Village of East Aurora: Reconnaissance Level Survey

659 Main Street c1930

Two-story brick commercial building, a good , notable design despite storefront modifications.

USN 02952.000177



660-8 Main Street c1910

Two-story brick commercial building, a good, notable design despite storefront modifications. Built on the site of the East Aurora Opera House (1894), which burned in 1908.

Previously inventoried in 1970s

USN 02952.000178



661 Main Street c1930

Two-story brick commercial building, a good, notable design despite storefront modifications.

USN 02952.000179



665-669 Main Street c1925

One and two-story brick commercial building, a good, notable design despite storefront modifications. Apparently constructed as a single building. Built as the Shirton's Laundry (left) and the East Aurora Hardware Co. (right).

USN 02952.000179 [667]

USN 02952.000180 [669]



Village of East Aurora: Reconnaissance Level Survey

671 Main Street 1925

North, Shelgren & Swift, architects

Two-story brick commercial building, built as a movie theater and offices, notable despite alterations and a significant presence along Main Street.

USN 02952.000182



672-4 Main Street 1911

Harris & Merritt, architects

Two-story brick and stone commercial building, a notable design; the east addition of 1925 was designed by Merritt. Built as the First National Bank of East Aurora.

Previously inventoried in 1970s
USN 02952.000183



685 Main Street 1840

Two-and-a-half-story brick house, a notable late example of the Federal style.

Previously inventoried in 1970s

USN 02952.000



702 Main Street c1920

Three-story brick commercial building, a good and largely intact design.

USN 02952.000189



Village of East Aurora: Reconnaissance Level Survey

706 Main Street 1890

R. A. & L. Bethune, architects

Two-story brick commercial building, built as the Bank of East Aurora. Although the first story has been greatly altered, it is significant for being designed by the firm of the first professional woman architect in the U.S.

Previously inventoried in 1970s
USN 02952.000191



719 Main Street c1870

Two-story frame commercial building which retains its storefront and original windows, significant as one of the best preserved commercial buildings on Main St.

USN 02952.000196



728 Main Street c1910

Three-story brick commercial building, a good and largely intact design.

USN 02952.000198



746 Main Street v1818

One-and-a-half-story frame house, an excellent and intact example of the Greek Revival style. Originally occupied by Nathaniel Fillmore.

Recommended NRE (I)

Previously inventoried in 1970s, 1980

USN 02952.000025 (D)



Village of East Aurora: Reconnaissance Level Survey

762 Main Street c1870

Two-story frame house, a well preserved vernacular example.

USN 02952.000027 (D)



771 Main Street v1814

One-and-a-half-story frame house, a notable example of the Federal style.

Previously inventoried in 1970s

USN 02952.000028 (D)



793 Main Street v1860

Two-story frame house, an exceptional late Greek Revival design.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1970s

USN 02952.000032 (D)



794 Main Street v1860

Two-and-a-half-story frame house, a well preserved vernacular example that retains the original carriage barn at rear.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973, 1981
USN 02952.000033 (D)



Village of East Aurora: Reconnaissance Level Survey

800 Main Street v1820

Two-story frame house, a well preserved vernacular example.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973, 1981

USN 02952.000034 (D)



807 Main Street 1913

Two-and-a-half-story frame house, a good, substantial example of the Craftsman style.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973

USN 02952.000035 (D)



810 Main Street v1825

Two-story frame house, a well preserved vernacular example.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973, 1981

USN 02952.000036 (D)



824 Main Street v1830

Two-story frame house, a well preserved vernacular example.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973, 1981

USN 02952.000038 (D)



Village of East Aurora: Reconnaissance Level Survey

835 Main Street v1956

One-story brick and frame house, a well preserved Modern design in the district.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973

USN 02952.000040 (D)



836 Main Street c1910

One-and-a-half-story frame house, a well preserved vernacular example.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973

USN 02952.000041 (D)



844 Main Street v1900

Two-and-a-half-story frame house, a good example of the American Foursquare with Queen Anne features.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973

USN 02952.000042 (D)



845 Main Street v1928

Two-story brick house, an intact and unusual Colonial Revival design.

Contributing building in the proposed East Main Street historic district.

Previously inventoried in 1973

USN 02952.000043 (D)



Village of East Aurora: Reconnaissance Level Survey

852 Main Street v1880

Two-and-a-half-story frame house
Outstanding, very well preserved example of the
Stick style. Recommended NRE (I)

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973, 1980
USN 02952.000044 (D)



853 Main Street v1870

Two-story frame house, an outstanding and well
preserved example of the Italianate style.

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973

USN 02952.000045 (D)



861 Main Street v1885

Two-and-a-half-story frame house, a very good
example of the Queen Anne style.

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973

USN 02952.000046 (D)



866 Main Street 1885

Two-and-a-half-story brick house, an
outstanding example of the Queen Anne style.

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973, 1981

USN 02952.000047 (D)



Village of East Aurora: Reconnaissance Level Survey

871 Main Street 1892

Two-and-a-half-story frame house
Outstanding, very well preserved example of the
Shingle style. Recommended NRE (I)

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973
USN 02952.000048 (D)



893 Main Street 1823

Two-story brick house, a notable Federal design
considered to be the oldest brick house in the
Village.

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973
USN 02952.000049



898 Main Street 1893

Two-and-a-half-story frame house, an
outstanding, very well preserved example of the
Queen Anne style. Recommended NRE (I)

Contributing building in the proposed East Main
Street historic district.

Previously inventoried in 1973, 1981
USN 02952.000050 (D)



34 Maple Road v1825

Two-story frame house, a notable, well
preserved vernacular example.

Previously inventoried in 1970s



Village of East Aurora: Reconnaissance Level Survey

77 Maple Road v1925

Two-and-a-half-story frame house, a very good example of Dutch Colonial Revival.



85 Maple Road v1948

One-story frame house, a good postwar example of the Cape Cod style.



103 Maple Road v1825

Two-story frame house, a well preserved vernacular example.



110 Maple Road v1914

One-and-a-half-story frame house, a very good example of a vernacular bungalow.



Village of East Aurora: Reconnaissance Level Survey

111 Maple Road v1930

Two-and-a-half-story frame house, a very good example of Dutch Colonial Revival.



118 Maple Road v1901

Two-story frame house, a well preserved vernacular example.



119 Maple Road v1900

Two-story frame house, a well preserved vernacular example.



129 Maple Road v1932

Two-and-a-half-story brick and frame house, a good Colonial Revival example.



Village of East Aurora: Reconnaissance Level Survey

159 Maple Road v1910

One-and-a-half-story frame house, a very good example of Dutch Colonial Revival.



169 Maple Road v1935

One-and-a-half-story frame house, an intact and very unusual example of Dutch Colonial Revival.



197 Maple Road v1930

Two-and-a-half-story frame house, a good Colonial Revival example.



177 Mill Road v1910

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.



Village of East Aurora: Reconnaissance Level Survey

332 Mill Road v1880

Two-and-a-half-story frame house, which appears to be a good, intact example of the Shingle style.



369 Mill Road v1920

Two-and-a-half-story frame barn, a very large and well detailed gambrel roof example.



272 North Street v1952

One-and-a-half-story frame house, a good example of the Craftsman style.



277 North Street v1947

One-and-a-half-story frame house, a good example of the postwar Cape Cod style.



Village of East Aurora: Reconnaissance Level Survey

285 North Street v1926

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.



300 North Street v1951

One-story brick house, an unusual example of the postwar Ranch house.



342 North Street v1915

Two-and-a-half-story frame house, a very good example of the Craftsman style.



358 North Street v1920

Two-and-a-half-story brick house, an intact and unusual Tudor Revival design.



Village of East Aurora: Reconnaissance Level Survey

410 North Street v1916

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.



440 North Street v1926

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.



446 North Street v1924

Two-story frame house, a well preserved vernacular example.



520 North Street v1920

Two-and-a-half-story frame house, a very good example of the Craftsman style.



Village of East Aurora: Reconnaissance Level Survey

526 North Street v1923

Two-and-a-half-story frame house, a good example of the Craftsman style.



14 North Grove Street 1924

Two-and-a-half-story frame house, a very good example of Dutch Colonial Revival. Built as the parsonage for the adjacent Christian Church.



28 North Grove Street v1900

Two-and-a-half-story frame house, a well preserved vernacular example.



69-71 North Grove Street c1925

One-and-a-half-story frame house, an unusual example of Dutch Colonial Revival. It may have been converted from the stable of 450 Fillmore Avenue.

Contributing building in the proposed Fillmore Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

72 North Grove Street c1920

One-and-a-half-story frame house, a very good example of a Craftsman bungalow despite a large rear addition.

Contributing building in the proposed Fillmore Avenue historic district.



76 North Grove Street v1900

Two-and-a-half-story frame house, a fine, unusual Colonial Revival example.

Contributing building in the proposed Fillmore Avenue historic district.



77 North Grove Street v1897

Two-and-a-half-story frame house, a very good example of the Shingle style.

Contributing building in the proposed Fillmore Avenue historic district.



83 North Grove Street c1895

Two-and-a-half-story frame house, an excellent and imposing example of the Shingle style.

Contributing building in the proposed Fillmore Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

89 North Grove Street v1895

Two-and-a-half-story frame house, a very good example of the Queen Anne style.

Contributing building in the proposed Fillmore Avenue historic district.



92 North Grove Street v1907

Two-and-a-half-story log house, a rare and well preserved example of this building type.

Contributing building in the proposed Fillmore Avenue historic district.



97 North Grove Street v1901

Two-and-a-half-story frame house, a very good example of the Queen Anne style.

Contributing building in the proposed Fillmore Avenue historic district.



107 North Grove Street v1885

Two-and-a-half-story frame house, a highly intact example of the Shingle style, with later rear additions. It retains the original carriage barn.

Contributing building in the proposed Fillmore Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

108 North Grove Street v1900

Two-and-a-half-story frame house

Contributing building in the proposed Fillmore Avenue historic district.



23 North Willow Street v1930

One-and-a-half-story frame house, a very good example of a Craftsman bungalow.



27 North Willow Street v1920

One-and-a-half-story frame house, a good example of a Craftsman bungalow.



31 North Willow Street v1913

Two-and-a-half-story frame house, a well preserved vernacular example.



Village of East Aurora: Reconnaissance Level Survey

53 North Willow Street v1920

One-and-a-half-story frame house, a good example of a Craftsman bungalow.



65 North Willow Street v1807

Two-story frame house, built for Phineas Stephens. Notable as the reputed oldest residence in the Village; moved here from Hamburg Street in 1975.



68 North Willow Street v1923

Two-and-a-half-story frame house, a good Colonial Revival example.



75 North Willow Street c1910

Two-and-a-half-story frame house, a very good example of the Craftsman style.



Village of East Aurora: Reconnaissance Level Survey

79 North Willow Street v1916

One-and-a-half-story frame house, an excellent example of a Craftsman bungalow.



85 North Willow Street v1925

One-and-a-half-story frame house, an outstanding Tudor Revival example.



100 North Willow Street v1920

Two-story frame house, an excellent Colonial Revival example.



121 North Willow Street c1870

Two-story frame house, an interesting Italianate style cottage that was moved here and modified about 1915.



Village of East Aurora: Reconnaissance Level Survey

129 North Willow Street v1927

One-and-a-half-story frame house, a good example of the Craftsman style.



138 North Willow Street v1915

One-and-a-half-story frame house, an excellent example of a Craftsman bungalow.



170 Oakwood Avenue c1900

One-and-a-half-story frame house, an unusual little example of a worker's cottage on a very large lot.



Oakwood Avenue at Willow Street

The Oakwood Cemetery, a traditional 19th century with linear graves shaded by an old growth tree canopy.



Village of East Aurora: Reconnaissance Level Survey

218 Oakwood Avenue v1880

Two-story frame house, a well preserved vernacular example that retains a board-and-batten stable and 20th century.

Contributing building in the proposed Oakwood Avenue historic district.



242 Oakwood Avenue c1890

Two-story frame house, a very unusual eclectic design that retains the original carriage barn.

Contributing building in the proposed Oakwood Avenue historic district.



257 Oakwood Avenue v1900

Two-and-a-half-story frame house, a well preserved vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



261 Oakwood Avenue v1924

One-and-a-half-story frame house, a very good example of the Craftsman style, complete with its highly original garage.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

262 Oakwood Avenue v1920

One-and-a-half-story frame house, a good example of the Craftsman style.

Contributing building in the proposed Oakwood Avenue historic district.



267 Oakwood Avenue v1927

Two-and-a-half-story frame house, a good Craftsman example with exposed rafter tails.

Contributing building in the proposed Oakwood Avenue historic district.



279 Oakwood Avenue v1961

One-story frame house, a good example of the Ranch house, apparently largely intact.

Contributing building in the proposed Oakwood Avenue historic district.



285 Oakwood Avenue v1895

Two-and-a-half-story frame house, a good vernacular example with an imposing stone front porch and carriage barn at rear.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

294 Oakwood Avenue v1886

Two-and-a-half-story frame house, an unusual Queen Anne style example with a carriage barn at rear; still notable despite the modifications to both.

Contributing building in the proposed Oakwood Avenue historic district.



302 Oakwood Avenue v1906

Two-and-a-half-story frame house, a well preserved vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



306 Oakwood Avenue v1902

Two-and-a-half-story frame house, an unusual and largely intact Queen Anne example.

Contributing building in the proposed Oakwood Avenue historic district.



323 Oakwood Avenue v1905

Two-and-a-half-story frame house, an excellent example of a Craftsman style foursquare.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

350 Oakwood Avenue v1920

Two-story frame house, a good example despite modern siding, as it still retains its original windows.

Contributing building in the proposed Oakwood Avenue historic district.



351 Oakwood Avenue v1905

One-and-a-half-story rusticated concrete block and frame house, a good example of the Craftsman style despite the installation of new windows.

Contributing building in the proposed Oakwood Avenue historic district.



354 Oakwood Avenue v1860

Two-and-a-half-story frame house, a good example of the Italianate style despite later additions, as it retains its original two-over-two round arch front windows.

Contributing building in the proposed Oakwood Avenue historic district.



357 Oakwood Avenue v1909

Two-and-a-half-story frame house, a large and well preserved vernacular example with rear carriage barn.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

360 Oakwood Avenue v1901

Two-story frame house, a well preserved example of small vernacular worker's cottage.

Contributing building in the proposed Oakwood Avenue historic district.



363 Oakwood Avenue v1910

Two-and-a-half-story frame house, an excellent example of the Craftsman style. The Scheidemantel house was placed on the National Register in 1993. 94NR00623

Contributing building in the proposed Oakwood Avenue historic district.

USN 02952.000075 (L)



369 Oakwood Avenue v1906

Two-and-a-half-story frame house, a good Colonial Revival example.

Contributing building in the proposed Oakwood Avenue historic district.



370 Oakwood Avenue v1871

Two-story frame house, an intact vernacular example, with a smaller rear frame dwelling.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

375 Oakwood Avenue v1914

Two-and-a-half-story frame house, a good, symmetrical example of the Craftsman style, despite the attached garage addition.

Contributing building in the proposed Oakwood Avenue historic district.



376 Oakwood Avenue v1890

Two-story frame house, a well preserved example with an intact carriage barn at rear.

Contributing building in the proposed Oakwood Avenue historic district.



382 Oakwood Avenue v1871

Two-story frame house, a well preserved example with an intact carriage barn at rear.

Contributing building in the proposed Oakwood Avenue historic district.



385 Oakwood Avenue c1880

Two-and-a-half-story frame house, an excellent example of the Stick style, one of the few such examples in the Village.

Contributing building in the proposed Oakwood Avenue historic district.

Previously inventoried in 1970s



Village of East Aurora: Reconnaissance Level Survey

404 Oakwood Avenue v1881

Two-and-a-half-story frame house, a well preserved example with an intact carriage barn at rear.

Contributing building in the proposed Oakwood Avenue historic district.

Previously inventoried in 1970s



405 Oakwood Avenue v1870

Two-and-a-half-story frame house, a good example of a 19th century vernacular house as remodeled in the early 20th century.

Contributing building in the proposed Oakwood Avenue historic district.

Previously inventoried in 1970s



415 Oakwood Avenue v1890

Two-and-a-half-story frame house, a very well preserved vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



423 Oakwood Avenue v1900

Two-and-a-half-story frame house, a very unusual example of a Colonial Revival foursquare; it may have recent modifications.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

429 Oakwood Avenue v1890

Two-and-a-half-story frame house, a very large and well preserved example with attached rear dwelling.

Contributing building in the proposed Oakwood Avenue historic district.



447 Oakwood Avenue v1876

Two-and-a-half-story frame house, a good example of the vernacular Italianate style that retains its wrap-around porch and unusual window hoods.

Contributing building in the proposed Oakwood Avenue historic district.



450 Oakwood Avenue v1876

Two-and-a-half-story frame house, a very well preserved example of the Italianate style, with exceptional original details and original 2-over-2 windows. Recommended NRE (I)

Contributing building in the proposed Oakwood Avenue historic district.

Previously inventoried in 1970s



461 Oakwood Avenue v1900

Two-story frame house, a well maintained vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

462 Oakwood Avenue v1890

Two-and-a-half-story frame house, a largely intact vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



472 Oakwood Avenue v1882

Two-story frame house, a good vernacular example despite a recent rear addition.

Contributing building in the proposed Oakwood Avenue historic district.



473 Oakwood Avenue c1890

Two-and-a-half-story frame house, a very good example of the Queen Anne style.

Contributing building in the proposed Oakwood Avenue historic district.



480 Oakwood Avenue v1880

Two-and-a-half-story frame house, a good, intact vernacular example.

Contributing building in the proposed Oakwood Avenue historic district.



Village of East Aurora: Reconnaissance Level Survey

481 Oakwood Avenue c1875

Two-story frame house, a good though simple example of the vernacular Italianate that was probably moved here in 1910.

Contributing building in the proposed Oakwood Avenue historic district.



515 Oakwood Avenue v1900

Two-story frame house, a good vernacular example notable for the unusual design of both the house and rear carriage barn.



520 Oakwood Avenue 1959

Pauley, Hauck & Welch, architects

Two-story brick school building, an excellent example of the International style, the best in the Village.

Recommended NRE (I)



531 Oakwood Avenue v1935

Two-and-a-half-story frame house, an excellent, well preserved example of the Tudor Revival style.



Village of East Aurora: Reconnaissance Level Survey

558 Oakwood Avenue v1876

Two-story frame house, a well preserved vernacular example.



592 Oakwood Avenue v1880

One-and-a-half-story frame house, a well preserved vernacular example.



610 Oakwood Avenue v1877

Two-story frame house, a well preserved vernacular example.



663 Oakwood Avenue c1900

Two-and-a-half-story frame commercial building, notable in spite of later siding for its intact details, especially the storefront.



Village of East Aurora: Reconnaissance Level Survey

677 Oakwood Avenue v1910

One-and-a-half-story rusticated concrete block and frame house, an excellent, very well preserved example of this distinctive exterior treatment.



Oakwood Avenue, east of Elm Street

The East Aurora Cemetery, a traditional 19th century with linear graves shaded by an old growth tree canopy.



750 Oakwood Avenue v1910

Two-and-a-half-story frame house, a good example of the American Foursquare.



764 Oakwood Avenue v1900

Two-and-a-half-story frame house, a well preserved vernacular example.



Village of East Aurora: Reconnaissance Level Survey

859 Oakwood Avenue v1890

Two-and-a-half-story frame house, an outstanding, well-preserved example of the Shingle style with later, sympathetic additions.

Recommended NRE (I)

Contributing building in the proposed East Main Street historic district.



31 Olean Street c1828

Two-story brick house, an example of an early Federal style building (the Riley double house), noteworthy despite later alterations.

Previously inventoried in 1970s

USN 02952.000014



62 Olean Street v1876

Two-story frame house, a well preserved vernacular example.



119 Olean Street v1890

Two-and-a-half-story frame house, an exceptional Queen Anne / Colonial Revival transitional design.

USN 02952.000074 (I)



Village of East Aurora: Reconnaissance Level Survey
